

Davis Engineering

Welding Supervisor

Knowledge Requirement

- Responsible for the overall quality of the welds
- Responsible for all weld inspections, including NDT
- Develop and maintain all weld procedures
- Certify Welders as required by providing training, testing, and qualifying of all staff welders
- Ensure all weld machines are maintained and calibrated
- Maintain a database of all welder certification
- Specify and request all weld related machinery and weld consumables
- Supervise a staff of trained and certified NDT inspectors including subcontract inspectors
- Support and enforce all company Health and Safety policies and procedures

Qualifications

- Must be CWB certified as a Weld Supervisor (or qualified to pass these tests)
- Must be fluent with the requirements of CWB, ASME,, and MIL-STD-2219
- Must be level 2 NDT certified (or qualified to pass these tests)

Salary – To be Negotiated

Note: Must be able to obtain NATO Secret Security Clearance.

Email resume to byoung@davis-eng.com or fax 613 748-3972, Attn B Young, 1260 Old Innes Road, Ottawa Ontario K1B 3V3, Website www.davis-eng.com